



Order Code..... **KT41**

POWER SUPPLY REPAIR KIT

POWER BOARD.....FSP228-3F01


TECO TL3281RT
VIEWSONIC N3260W

Fault Symptoms

Dead
No stand by voltage

Tip.....

Check all the capacitors in the output of the power supply for low capacitance



Circuit Reference

F1
Q4
IC2
ZD4
Q9
Q7
Q11
CS21
CS22
IC1
R65
R28
R29

Description

T4A
8N60C
1532
BZV55C
BC858
BC848
BC858
1500UF
1500UF
L6598D
5R6
510
510

We recommend all kits are fitted by qualified engineers

We accept no responsibility for loss, injury or damage caused by your use of this kit as a successful repair depends on your own skill and fault finding ability.